

EXTRA REQUIREMENTS:	CHANGE MANAGEMENT:	HANKING	TERMINATIONS / FURTHER COMMENTS:
PACKAGING OUTER100			Each Power Lead to be individually polybagged.
PIN PROTECTING COVERNO			
WIRING INSTRUCTIONSNO		None	
PRE-SHIPMENT INSPECTION REQUIREDNO			
COMMENTS:			